




Returning a Kodiak Oxygen System for 5 year ICA/DOT Overhaul



Service is for the 115 cu. ft. and 50 cu. ft. bottles

WIRE HARNESS MUST BE INCLUDED FOR TESTING AND RECERTIFICATION. YOU CAN FIND THE HARNESS ATTACHED TO REGULATOR FROM THE TRANSDUCER.

Service Pricing and Lead Time

- ❖ Service cost to overhaul regulator assembly with hydrostatic bottle testing \$1,795.00 with a 10-12 business day lead time
- ❖ Service cost to overhaul the regulator with the purchase of a new bottle is \$3,995.00
 - 115cu ft cylinders and 50cu ft cylinders must be removed from service and replaced with new every 15 years.
 - There is a longer lead time for this service. Please reach out to Customer Service for details.

5 year ICA/DOT Overhaul Service Includes:

- Complete tear down of the regulator assembly. All O-Rings, seals, fitting and hardware will be replaced. All assembly parts will be cleaned and inspected for damage and functionality (the cost for any damaged or non-functional parts will be quoted before service begins). The system will be reassembled and tested for full functionality.
- Bottle hydrostatic testing.
- Up to 4 A5 flowmeter overhauls. Service includes the replacement of tubing, O-Rings and functional testing.
- Four replacement standard, clear masks and four replacement oxymizer cannulas.
- A completed 8130-3 form to show overhaul of the oxygen system for use.

Service Includes A5 Flowmeter Overhauls only. We no longer support the A4 and A3 Flowmeters.

