




100 Series Comprehensive Service

Flat Rate Service Cost and Lead Time

Service Cost: \$1,999.00

Lead Time: 7-10 Business Days



Comprehensive Overhaul Service Includes:

- Initial inspection, troubleshooting and cleaning.
- Repair and replacement of all broken, damaged, and worn internal components. All life limited components will be replaced, and the units will be zero timed.
- All labor costs.
- Final testing in accordance with PFI Specifications.
- Completed 8130-3 documentation.
- 2-year Extended Warranty – Covers testing/inspection, repair or replacement of defective part, labor, return ground shipping (domestic).

What we need from you: Both SpeedBrake Cartridges (we will not service a single cartridge).

63354 Powell Butte Road, Bend, OR 97701 PH: 1.800.547.2558

customerservice@preciseflight.com