




Returning a Precise Flight Fixed Oxygen System for 5 year ICA/DOT Overhaul



3 Bottle System

WIRE HARNESS MUST BE INCLUDED FOR TESTING AND RECERTIFICATION. YOU CAN FIND THE HARNESS ATTACHED TO REGULATOR FROM THE TRANSDUCER.

Service Pricing and Lead Time

❖ Service cost with hydrostatic bottle testing or exchange bottles: \$1,495.00 with a 10-17 business day lead time (please refer to Bottle Exchange Program details below.)

5 year ICA/DOT Overhaul Service Includes:

- Complete tear down of the regulator assembly. All O-Rings, seals, and hardware including 9 - SEC seals. All assembly parts will be cleaned and inspected for damage and functionality (the cost for any damaged or non-functional parts will be quoted before service begins). The system will be reassembled and tested for full functionality.
- Bottle hydrostatic testing or exchange bottles.
- Up to 4 A5 flowmeter overhauls. Service includes the replacement of tubing, O-Rings and functional testing.
- Four replacement standard, clear masks and four replacement oxymizer cannulas.
- A completed 8130-3 form to show overhaul of the oxygen system for use.



*Service Includes **A5 Flowmeter Overhauls** only. We no longer support the A4 and A3 Flowmeters.*



BOTTLE EXCHANGE PROGRAM

Precise Flight has developed an exchange program to reduce the downtime for aircraft due to maintenance requirements for oxygen systems.

- To maintain quick overhaul lead times, your bottles will be exchanged for another certified hydrostatically tested bottle from our exchange pool. This ensures that the overhaul process is relatively quick, on average 10-12 business days.
- If you wish to keep your original bottles, please specify when requesting your RMA. Please note that the turn time for a hydrostatic test on your original bottle will take up to 12-17 business days.

Exchange Program Qualifications: Bottles with significant scratches and/or damage will not be eligible for the exchange program.

Expedited service may be available for a \$275.00 fee. Please request expedited service prior to shipping your Oxygen System to allow for scheduling.

Precise Flight, Inc. Customer Service | customerservice@preciseflight.com | 1.800.547.2558

Ship to: 63354 Powell Butte Rd. Bend, OR 97701