



Returning a Precise Flight Pulselite for maintenance and repair

When sending in your Pulselite for maintenance, Precise Flight will inspect and test your unit. You will receive a quote within 3 business days. Standard lead times for service and repair is 10-12 business days after the quote is approved. If there is no fault found with the unit upon testing a \$195.00 inspection and recertification fee will apply. If the unit is found to be unrepairable, a replacement can be purchased through our Sales Department.

***Warranty Repair: All Pulselite units will need to be tested and inspected before warranty approval. ***

Non-Warranty Flat Rate Repair Costs

MODEL	P/N	PRICE
1150B	006P0002-1	\$1,375.00
1150S-4	006P0001-1	\$1,375.00
1150S-6	006P0007-1	\$1,375.00
1151	020P0001-1	\$1,375.00
1151D	020P0026-1	\$1,375.00
1152B	020P0002-2	\$1,375.00
2401	020P0003-1	\$1,375.00
2401S	020P0015-1	\$1,375.00
2401D	020P0029-1	\$1,375.00
3060	025P0004-1	\$1,375.00
3060A	025P0005-1	\$1,375.00
3060S	025P0006-1	\$1,375.00

1210	015P001A-2	REPLACE	Contact sales@preciseflight.com for price and availability.
1220	015P001A-1	REPLACE	Contact sales@preciseflight.com for price and availability.

1150	OBSOLETE	REPLACE	Contact sales@preciseflight.com for price and availability.
2400	OBSOLETE	REPLACE	Contact sales@preciseflight.com for price and availability.

Inspection and recertification	\$195.00
--------------------------------	----------

Email customerservice@preciseflight.com for an RMA Request Form.