



Returning a Precise Flight Pulselite for maintenance and repair

When sending in your Pulselite for maintenance, Precise Flight will inspect and test your unit. After the inspection is complete, we will contact you with the findings. Standard lead times for service and repair is 5-7 business days after the quote is approved. If there is no fault found with the unit upon testing a \$150.00 inspection and recertification fee will apply. If the unit is found to be unrepairable, a replacement can be purchased through our Sales Department.

***Warranty Repair: All Pulselite units will need to be tested and inspected before warranty approval. ***

Non-Warranty Flat Rate Repair Costs

| MODEL | P/N | PRICE |
|---------|------------|-----------|
| 1150B | 006P0002-1 | \$999.00 |
| 1150S-4 | 006P0001-1 | \$999.00 |
| 1150S-6 | 006P0007-1 | \$999.00 |
| 1151 | 020P0001-1 | \$1299.00 |
| 1151D | 020P0026-1 | \$999.00 |
| 1152B | 020P0002-2 | \$1099.00 |
| 2401 | 020P0003-1 | \$999.00 |
| 2401S | 020P0015-1 | \$999.00 |
| 2401D | 020P0029-1 | \$999.00 |
| 3060 | 025P0004-1 | \$999.00 |
| 3060A | 025P0005-1 | \$999.00 |
| 3060S | 025P0006-1 | \$999.00 |

| | | | |
|------|------------|---------|--|
| 1210 | 015P001A-2 | REPLACE | Contact sales@preciseflight.com for price and availability. |
| 1220 | 015P001A-1 | REPLACE | Contact sales@preciseflight.com for price and availability. |

| | | | |
|------|----------|---------|--|
| 1150 | OBSOLETE | REPLACE | Contact sales@preciseflight.com for price and availability. |
| 2400 | OBSOLETE | REPLACE | Contact sales@preciseflight.com for price and availability. |

| | |
|--------------------------------|----------|
| Inspection and recertification | \$150.00 |
|--------------------------------|----------|

Email customerservice@preciseflight.com for an RMA Request Form.